

Inspection Photos

API: 017-07666

Operator: **MYSTIQUE RESOURCES COMPANY**

Inspection Date: 8/28/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east at the associated tank battery location. This area was planted to corn but the corn did not establish and there are undesirable weeds.



Inspection Photos



Photo 2. Facing east at the associated tank battery location. This area was planted to corn but the corn did not establish and areas of no crop growth.



Inspection Photos



Photo 3. Drone aerial photo facing east down toward the associated tank battery location. There is impacted crop growth in this area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos




Photo 4. Facing north toward the access road and abandoned wellsite. The crop appears to have uniformly reestablished.



Inspection Photos




Photo 5. Facing north overlooking the abandoned wellsite. The crop appears to have uniformly reestablished.



Inspection Photos



Photo 6. Facing south overlooking the abandoned wellsite. The crop appears to have uniformly reestablished.

