

Inspection Photos
Location Name: Walsh 2
Location ID: 318151



Photo 1 location



Photo 2 Wellhead sign

Inspection Photos
Location Name: Walsh 2
Location ID: 318151



Photo 3 Wellhead SI LOTO



Photo 4 Location

Inspection Photos
Location Name: Walsh 2
Location ID: 318151



Photo 5 ECD SI, LOTO



Photo 6 Horizontal Heated Separator SI, LOTO



Inspection Photos
Location Name: Walsh 2
Location ID: 318151



Photo7 Gas Meter Run SI, LOTO card indicates current calibration



Photo 8 Walsh compressor

Inspection Photos
Location Name: Walsh 2
Location ID: 318151



Photo 9 Tank Battery



Photo 10 Updated TB sign



Inspection Photos
Location Name: Walsh 2
Location ID: 318151



Photo 11 Tank Battery