

Inspection Photos

ID: 480502

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 8/28/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest toward the Arapahoe Unit Tank Battery/Sec. 28. There is no secondary containment of the red tank.



Inspection Photos



August 28, 2024
+38.813133,-102.112220

Photo 2. There is unused equipment on location with rusted out flowlines and a burnt fiberglass tank.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

ID: 480502 | Date: 8/28/2024

Inspection Photos



Photo 3. Facing west at the location. The red tank is in use and has no secondary containment or labeling.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

ID: 480502 | Date: 8/28/2024

Inspection Photos



Photo 4. There is a pile of material likely from the tank battery berms which contains pieces of pipe and oil stained soils. Impacted material must be removed and properly disposed.



Inspection Photos



Photo 5. Facing south at the location..



Inspection Photos



Photo 6. This area was excavated and tapped into with the flexible hose.



Inspection Photos



Photo 7. Facing toward the tank battery at worst side of the location..



Inspection Photos



Photo 8. Facing southeast toward the wellsite just south of the tank battery facility.

