

Inspection Photos

ID: 480511

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 8/28/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest toward the Arapahoe Unit Tank Battery/Sec. 27. There is oily material along the berm at red arrows and at the truck load out pipe.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID: 480511 | Date: 8/28/2024

Inspection Photos



Photo 2. This secondary containment is full of oil with no wildlife protections/netting. This needs to be immediately drained and properly disposed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID: 480511 | Date: 8/28/2024

Inspection Photos



Photo 3. On the west side of the tanks there is oil staining from a leak that occurred.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID: 480511 | Date: 8/28/2024

Inspection Photos




Photo 4. There is oil saturated soils at the base of the tank that must be cleaned up.



Inspection Photos



Photo 5. Facing east at the north side of the tanks. There is oil saturated soils at the base of the tank that must be cleaned up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID: 480511 | Date: 8/28/2024