

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL HAGEN-67S95W/16NESE

Location ID: 335041

Date: 8/28/2024



Location Entrance – Photo #03085



Wellheads – Photo #03087

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL HAGEN-67S95W/16NESE

Location ID: 335041

Date: 8/28/2024



Separators – Photo #03088



Tank Battery – Photo #03086

Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL HAGEN-67S95W/16NESE

Location ID: 335041

Date: 8/28/2024



ECD/Gas Meter – Photo #03089