

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad
Location #: 334069



**Location Overview: Location is within Black Bear Habitat area
& in close proximity to High Priority/NSO Habitat areas.
Location is approximately 500 yards from Middle Mamm
Creek.**

Section/Township/Range: 1 8S93W

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad
Location #: 334069



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad
Location #: 334069



Photo # 7324 Failure to maintain chemical BMP - Chemical tank containment approximately 3/4 full of fluid/BMP insufficient to contain possible spill

Photo # 7325 Failure to maintain chemical BMP - Chemical tank containment approximately 3/4 full of fluid/BMP insufficient to contain possible spill

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad
Location #: 334069



Photo # 7326 Failure to maintain chemical BMP - Chemical tank containment approximately 3/4 full of fluid/BMP insufficient to contain possible spill

Photo # 7327 Failure to maintain chemical BMP - Chemical tank containment approximately 3/4 full of fluid/BMP insufficient to contain possible spill