

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/15SESE

Location ID: 335471

Date: 8/29/2024



Location Entrance – Photo #03118



Wellheads – Photo #03119

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/15SESE

Location ID: 335471

Date: 8/29/2024



Aug 29, 2024 at 12:23:05  
Parachute CO 81635  
United States

Separators – Photo #03130



Aug 29, 2024 at 12:19:13  
Glenwood Springs CO  
United States

Tank Battery – Photo #03121

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/15SESE

Location ID: 335471

Date: 8/29/2024



**Pit – Photo #03133**



**Damaged Fencing – Photo #03122**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/15SESE

Location ID: 335471

Date: 8/29/2024



**Damaged Fencing – Photo #03124**



**Damaged Fencing – Photo #03132**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/15SESE

Location ID: 335471

Date: 8/29/2024



Open-Ended Load Line – Photo #03123



Transport of Sediment Offsite – Photo #03127

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/15SESE

Location ID: 335471

Date: 8/29/2024



Transport of Sediment Offsite – Photo #03128



Trash – Photo #03129