

**Inspection Photos**  
**Operator: Simcoe LLC**  
**Location Name: Le Platt B 1**  
**API: 05-067-08931**



**1. Lease sign**



**2. Pumping unit**

**Inspection Photos**  
**Operator: Simcoe LLC**  
**Location Name: Le Platt B 1**  
**API: 05-067-08931**



**3. Ancillary equipment**



**4. Production equipment**



**Inspection Photos**  
**Operator: Simcoe LLC**  
**Location Name: Le Platt B 1**  
**API: 05-067-08931**



**5. Damaged steel ring containment**



**6. North side of water tank**

**Inspection Photos**  
**Operator: Simcoe LLC**  
**Location Name: Le Platt B 1**  
**API: 05-067-08931**



**7. Tire tracks leading up to containment**



**8. East side of water tank**