

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-32 SESE Production Equipment

Location ID: 451928



Location


Separators



Inspection Photos

Location Name: Anschutz Equus Farms 4-62-32 SESE Production Equipment

Location ID: 451928



Gaslift risers



Unused Equipment

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-32 SESE Production Equipment

Location ID: 451928



Unused equipment



Unused equipment

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-32 SESE Production Equipment

Location ID: 451928



Unmarked Riser

