

Inspection Photos
Location Name: Malo 09-20
Location ID: 330637



Photo 1 – Tank Battery



Photo 2 – Nitrogen Tank and Heater Treater

Inspection Photos
Location Name: Malo 09-20
Location ID: 330637



Photo 3 – Heater Treater and ECD



Photo 4 – Wellhead

Inspection Photos
Location Name: Malo 09-20
Location ID: 330637



Photo 5 – Tag on Master Valve



Photo 6 – Wellhead Sign

Inspection Photos
Location Name: Malo 09-20
Location ID: 330637



Photo 7 – Pumping Unit