

Inspection Photos
Location Name: Wade 2-29
Location ID: 330957



Photo 1 – Tank Battery

Photo 2 – Tank Battery

Inspection Photos
Location Name: Wade 2-29
Location ID: 330957



Energy and Carbon Management Commission
40.63956, -103.99743, 4824.2ft
08/22/2024 12:42:30



Energy and Carbon Management Commission
40.63924, -103.99705, 4822.1ft
08/22/2024 12:42:56

Photo 3 – Heater Treater and ECD

Photo 4 – Pumping Unit

Inspection Photos
Location Name: Wade 2-29
Location ID: 330957



Energy and Carbon Management Commission
40.63924, -103.99705, 4816.3ft
08/22/2024 12:43:02

Photo 5 – Wellhead Sign



Energy and Carbon Management Commission
40.63923, -103.99701, 4826.1ft
08/22/2024 12:43:14

Photo 6 – Wellhead

Inspection Photos
Location Name: Wade 2-29
Location ID: 330957



Photo 7 – Wellhead Tag



Photo 8 – Tank Battery Sign