

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-33 SWNW Production Equipment

Location ID: 437847



August 27, 2024 at 9:37 AM
+40.2708, -104.3382
44° NE
Weld County
Energy & Carbon Management Commission



Location

Separators

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-33 SWNW Production Equipment

Location ID: 437847



Gas lift risers



Unmarked Riser

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-33 SWNW Production Equipment

Location ID: 437847



Line Heater. Missing Bird Protector



Missing Bird Protector

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-33 SWNW Production Equipment

Location ID: 437847



Missing Bird Protector



Missing Bird Protector