

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403908015

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: NOBLE ENERGY INC	Operator No: 100322	Phone Numbers
Address: 1099 18TH STREET SUITE 1500		Phone: (970) 730-7281
City: DENVER State: CO Zip: 80202		Mobile: ()
Contact Person: Dan Peterson	Email: rbueuf27@chevron.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 25474 Initial Form 27 Document #: 403184327

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

Yes Multiple Facilities

Facility Type: WELL	Facility ID: _____	API #: 123-27010	County Name: WELD
Facility Name: KISSLER K 21-32D	Latitude: 40.295443	Longitude: -104.789484	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: NWSW	Sec: 21	Twp: 4N	Range: 66W Meridian: 6 Sensitive Area? Yes
Facility Type: SPILL OR RELEASE	Facility ID: 484535	API #: _____	County Name: WELD
Facility Name: Kissler K21-32D	Latitude: 40.295411	Longitude: -104.789457	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: NWSW	Sec: 21	Twp: 4N	Range: 66W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications SW _____

Most Sensitive Adjacent Land Use Crop Land _____

Is domestic water well within 1/4 mile? Yes _____

Is surface water within 1/4 mile? Yes _____

Is groundwater less than 20 feet below ground surface? No _____

Other Potential Receptors within 1/4 mile

Freshwater Pond 0.12mi N, 0.18/0.23mi NW
Riverine 0.09mi NW, 0.22mi SE
Residential 0.13/0.18mi SW, 0.12/0.13/0.17/0.19mi NW
Farm Structures 0.11/0.13mi SW, 0.12/0.13/0.22/0.24mi NW
Commercial Structure 0.12mi NW

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input checked="" type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input checked="" type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	NA	Lab analysis if encountered
Yes	SOILS	10'x10'x5' below ground surface	Lab analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Pursuant to COGCC Rule 911 a site investigation was conducted pertaining to the KISSLER K21-32D wellhead cut and cap and flowline abandonment. The flowline was abandoned in place per a signed landowner agreement, and the Form 44 document number is 403540450, which is included under Related Forms. The wellhead was cut and capped per COGCC rules. Additionally, soil samples will be collected via hand auger at the directional changes on the attached proposed site investigation map (FL01-C through FL01-G). The Flowline Pre-Abandonment Notice Document number is included under Related Forms.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

A grab soil sample was collected at the base of the excavation or the area showing the highest degree of impact during field screening activities at the wellhead excavation. Additionally, soil samples will be collected via hand auger at the directional changes on the attached proposed site investigation map (FL01-C through FL01-G). A grab confirmation soil sample was collected at the wellhead excavation. Soil samples will be analyzed by a certified laboratory for TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons) organic compounds in soil per COGCC Table 915-1, and EC, SAR, pH, and boron. All samples collected were analyzed by a certified laboratory using approved COGCC laboratory analysis methods.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

If groundwater is encountered during the site investigation a grab groundwater will be collected and analyzed for all organic compounds per COGCC Table 915-1.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Visual inspection of the wellhead and flowline areas occurred during abandonment activities. During the flowline hand auger investigation to obtain flowline direction change samples, field personnel will field screen all disturbed areas using visual and olfactory senses to determine if laboratory confirmation sampling is required. The COGCC Flowline Closure Checklists will be utilized during the abandonment process. A photolog will be submitted on the Subsequent Form 27.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 13
Number of soil samples exceeding 915-1 7
Was the areal and vertical extent of soil contamination delineated? No
Approximate areal extent (square feet) 100

NA / ND

ND Highest concentration of TPH (mg/kg) _____
-- Highest concentration of SAR 2.77
BTEX > 915-1 No
Vertical Extent > 915-1 (in feet) 5

Groundwater

Number of groundwater samples collected 0
Was extent of groundwater contaminated delineated? No
Depth to groundwater (below ground surface, in feet) _____
Number of groundwater monitoring wells installed _____
Number of groundwater samples exceeding 915-1 _____

Highest concentration of Benzene (µg/l) _____
Highest concentration of Toluene (µg/l) _____
Highest concentration of Ethylbenzene (µg/l) _____
Highest concentration of Xylene (µg/l) _____
Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
_____ Number of surface water samples exceeding 915-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Five background soil samples were collected near the wellhead and analyzed for arsenic and pH. Background soil samples were collected from 5 feet below ground surface (ft bgs). The maximum background concentrations for pH was observed to be 8.97. The maximum background concentrations with a 1.25x multiplier applied for arsenic was calculated to be 5.73 mg/kg. All arsenic concentrations observed during decommissioning and the remedial excavation were below background levels. As such, arsenic should not be considered a contaminant of concern pursuant to spill/release ID 484535.

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____

Is further site investigation required?

A supplemental site investigation (SSI) will be completed to vertically and horizontally delineate the pH exceedance identified at SS04@5' during the remedial excavation. A proposed SSI map is attached to this Form 27. Based on the successful removal of all soil impacted with organic compounds above ECMC Table 915-1, and the evidence presented herein to eliminate arsenic as a contaminant of concern, Noble proposes to limit the SS04@5' SSI soil sampling to pH. Concurrently with the SSI, additional background samples will be collected to determine if the elevated pH is attributed to native soil conditions at the site. The SSI will be completed in accordance with the proposed implementation schedule, and the results of the SSI will be submitted on a subsequent Form 27.

The flowline associated with this wellhead has been abandoned in place in accordance with Form 44 Document #403540450. As such, soil samples will be collected via hand auger at the directional changes on the attached proposed site investigation map (FL01-C through FL01-G). Soil samples FL01-C through FL01-G were selected to satisfy the proposed sample locations outlined in the initial Form 27 (ECMC Document #403184327) Pursuant to direction change samples FL01-C through FL01-G, soil samples will be collected and analyzed in accordance with the Site Investigation Plan section of this Form 27.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

The source identified during decommissioning at sample location FL01-A@5' was successfully removed through a remedial excavation. A detailed remedial excavation report is attached to this Form 27. A total of 98 cubic yards of impacted soil was excavated and transported off-site for disposal at the Waste Management Buffalo Ridge Landfill.

A supplemental site investigation (SSI) will be completed to vertically and horizontally delineate the pH exceedance identified at SS04@5' during the remedial excavation. A proposed SSI map is attached to this Form 27. Based on the successful removal of all soil impacted with organic compounds above ECMC Table 915-1, and the evidence presented herein to eliminate arsenic as a contaminant of concern, Noble proposes to limit the SS04@5' SSI soil sampling to pH. Concurrently with the SSI, additional background samples will be collected to determine if the elevated pH is attributed to native soil conditions at the site. The SSI will be completed in accordance with the proposed implementation schedule, and the results of the SSI will be submitted on a subsequent Form 27.

The flowline associated with this wellhead has been abandoned in place in accordance with Form 44 Document #403540450. As such, soil samples will be collected via hand auger at the directional changes on the attached proposed site investigation map (FL01-C through FL01-G). Soil samples FL01-C through FL01-G were selected to satisfy the proposed sample locations outlined in the initial Form 27 (ECMC Document #403184327) Pursuant to direction change samples FL01-C through FL01-G, soil samples will be collected and analyzed in accordance with the Site Investigation Plan section of this Form 27.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

NA

Soil Remediation Summary

In Situ

Ex Situ

_____ Bioremediation (or enhanced bioremediation)

Yes _____ Excavate and offsite disposal

_____ Chemical oxidation

_____ If Yes: Estimated Volume (Cubic Yards) _____ 98

_____ Air sparge / Soil vapor extraction

_____ Name of Licensed Disposal Facility or ECMC Facility ID # _____

_____ Natural Attenuation

_____ Excavate and onsite remediation

_____ Other _____

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report
 Other Remedial Excavation Report

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policy MWZZ 316714) and financial assurance in compliance with COGCC rules. Records are available on the COGCC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

NA

Volume of E&P Waste (solid) in cubic yards 98

E&P waste (solid) description Soil

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility: Waste Management Buffalo Ridge Landfill

Volume of E&P Waste (liquid) in barrels 0

E&P waste (liquid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards?

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with COGCC 1000 Series Rules.

Is the described reclamation complete? No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim

Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 02/01/2023

Proposed date of completion of Reclamation. 12/03/2025

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 07/20/2022

Actual Spill or Release date, or date of discovery. 05/26/2023

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 02/01/2023

Proposed site investigation commencement. 09/03/2024

Proposed completion of site investigation. 03/03/2025

REMEDIAL ACTION DATES

Proposed start date of Remediation. 11/17/2023

Proposed date of completion of Remediation. 06/03/2025

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

The implementation schedule has been changed due to the decommissioning of the Kissler K21-32D wellhead/flowline and necessity for supplemental site investigation activities adjacent to the wellhead/flowline. The proposed site investigation will be completed following the approval of this form, landowner negotiations, and crew availability.

OPERATOR COMMENT

This Form 27 is being submitted to include the remedial excavation results for the Kissler K21-32D Wellhead/Flowline, and a proposal to complete a supplemental site investigation along the flowline.

Five background soil samples were collected near the wellhead and analyzed for arsenic and pH. Background soil samples were collected from 5 feet below ground surface (ft bgs). The maximum background concentrations for pH was observed to be 8.97. The maximum background concentrations with a 1.25x multiplier applied for arsenic was calculated to be 5.73 mg/kg. All arsenic concentrations observed during decommissioning and the remedial excavation were below background levels. As such, arsenic should not be considered a contaminant of concern pursuant to spill/release ID 484535.

A supplemental site investigation (SSI) will be completed to vertically and horizontally delineate the pH exceedance identified at SS04@5' during the remedial excavation. A proposed SSI map is attached to this Form 27. Based on the successful removal of all soil impacted with organic compounds above ECMC Table 915-1, and the evidence presented herein to eliminate arsenic as a contaminant of concern, Noble proposes to limit the SS04@5' SSI soil sampling to pH. Concurrently with the SSI, additional background samples will be collected to determine if the elevated pH is attributed to native soil conditions at the site. The SSI will be completed in accordance with the proposed implementation schedule, and the results of the SSI will be submitted on a subsequent Form 27.

The flowline associated with this wellhead has been abandoned in place in accordance with Form 44 Document #403540450. As such, soil samples will be collected via hand auger at the directional changes on the attached proposed site investigation map (FL01-C through FL01-G). Soil samples FL01-C through FL01-G were selected to satisfy the proposed sample locations outlined in the initial Form 27 (ECMC Document #403184327) Pursuant to direction change samples FL01-C through FL01-G, soil samples will be collected and analyzed in accordance with the Site Investigation Plan section of this Form 27.

Quarterly reporting will be conducted until closure criteria are achieved for the remediation project. The results of the supplemental site investigation will be submitted on a subsequent Form 27.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Allan Engelhardt

Title: Environmental Consultant

Submit Date: _____

Email: chevroneform@tasman-geo.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____

Date: _____

Remediation Project Number: 25474

COA Type

Description

0 COA	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

403908080	REMEDATION PROGRESS REPORT
403908094	SITE INVESTIGATION PLAN
403908133	SITE INVESTIGATION PLAN

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)