

Inspection Photos
Operator: Simcoe LLC
Location Name: Ludwig 2
API: 05-067-08296



1. Location entrance with tall weeds on south edge of location



2. Location overview

Inspection Photos
Operator: Simcoe LLC
Location Name: Ludwig 2
API: 05-067-08296



3. Pumping unit



4. Production equipment on north side of location



Inspection Photos
Operator: Simcoe LLC
Location Name: Ludwig 2
API: 05-067-08296



5. Pig station on south side of production equipment



6. Trailers and snow removal equipment stored on west side of location