

Inspection Photos

Operator: Simcoe LLC

Location: Gary Beebe 1 API: 067-06856

Location: Gary Beebe 3 API: 067-09413



Brian Welsh SE Field Inspector COGCC
37.20951, -107.65551, 6855.7ft
08/30/2024 11:48:52

1. Lease signs at edge of location



Brian Welsh SE Field Inspector COGCC
37.2097, -107.65533, 6842.0ft
08/30/2024 11:49:55

2. Meter shed and telemetry equipment on south side of location is for midstream use

Inspection Photos

Operator: Simcoe LLC

Location: Gary Beebe 1 API: 067-06856

Location: Gary Beebe 3 API: 067-09413



Brian Welsh SE Field Inspector COGCC
37.20988, -107.65535, 6856.8ft
08/30/2024 11:51:47

3. Gary Beebe B 1 wellhead



Brian Welsh SE Field Inspector COGCC
37.21007, -107.65558, 6846.5ft
08/30/2024 11:55:27

4. Gary Beebe B 3 pumping unit



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp #715200859-60

Inspection Photos
Operator: Simcoe LLC
Location: Gary Beebe 1 API: 067-06856
Location: Gary Beebe 3 API: 067-09413



5. Trackhoe stored on west side of location



6. Production equipment

Inspection Photos

Operator: Simcoe LLC

Location: Gary Beebe 1 API: 067-06856

Location: Gary Beebe 3 API: 067-09413



7. Water tank



8. Erosion on access near location

