

Inspection Photos

Operator: Simcoe LLC

Location: Gary Patrick 2 API: 067-09690

Location: Gary Patrick 4 API: 067-09691

Location: Sparks B 2 API: 067-09693

Location: Sparks B 4 API: 067-09692



Brian Welsh SE Field Inspector COGCC
37.16295, -107.63754, 6778.9ft
08/30/2024 14:26:40

1. Lease signs at edge of location



Brian Welsh SE Field Inspector COGCC
37.16244, -107.63814, 6673.7ft
08/30/2024 14:27:53

2. Pumping unit and linear pumps



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp #715200862-65

Inspection Photos

Operator: Simcoe LLC

Location: Gary Patrick 2 API: 067-09690

Location: Gary Patrick 4 API: 067-09691

Location: Sparks B 2 API: 067-09693

Location: Sparks B 4 API: 067-09692



3. Gary Patrick 2 wellhead and pump.
Remove and remediate stained rock
and soil around wellhead



4. Gary Patrick 4 wellhead and pump.
Remove and remediate stained rock
and soil around wellhead



Inspection Photos

Operator: Simcoe LLC

Location: Gary Patrick 2 API: 067-09690

Location: Gary Patrick 4 API: 067-09691

Location: Sparks B 2 API: 067-09693

Location: Sparks B 4 API: 067-09692



5. Water tank with electric sump pump

