

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/9SEW

Location ID: 335753

Date: 8/29/2024



Location Entrance – Photo #03157



Wellheads – Photo #03161

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/9SEW

Location ID: 335753

Date: 8/29/2024



Separators/Gas Meter – Photo #03159



Tank Battery – Photo #03158

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/9SEW

Location ID: 335753

Date: 8/29/2024



Pit – Photo #03160