


Inspection Photos

Location: CAERUS PICEANCE LLC STORY GULCH UNIT-64S96W/26SENW

Location ID: 335669

Date: 8/28/2024



Location - Photo #05127



Entrance to location/Frac Operations - Photo #05128

Inspection Photos

Location: CAERUS PICEANCE LLC STORY GULCH UNIT-64S96W/26SENW

Location ID: 335669

Date: 8/28/2024



Frac Operations - Photo #05131



Frac Operations - Photo #05136

Inspection Photos

Location: CAERUS PICEANCE LLC STORY GULCH UNIT-64S96W/26SENW

Location ID: 335669

Date: 8/28/2024



No labeling on Frac tank/Diesel tank - Photo #05160



No labeling on Frac tank/Diesel tank - Photo #05161