

Inspection Photos

August 23rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 326575

Inspection Document #: 714001143

La Plata County, CO

Township: NWNE 29 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hancock 2
Location ID: 326575



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: Hancock 2
Location ID: 326575



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the western interim reclamation area facing Northwest.

API #: 067-08336

Inspection Photos
Location Name: Hancock 2
Location ID: 326575



Photo 3. Soil staining/impacted surface material observed at the well head and generator.

Inspection Photos
Location Name: Hancock 2
Location ID: 326575



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area comprised of Squirrel tail, Pine and Gambel oak.

API #: 067-08336