

Inspection Photos

August 23rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 326590

Inspection Document #: 714001146

La Plata County, CO

Township: NWSE 27 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO


**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Streeter B 2
Location ID: 326590



8/23/24
+37.259165,-107.633556
114° SE



8/23/24
+37.269112,-107.621200
153° SE

STREETER B 2
SIMCOE LLC
ELEVATION: 7124 API #: 05-067-08357 DWR #: 70629-F
NAME OF TRIBE: N/A LEASE TYPE: FEE
LEASE#: N/A CA#: N/A
SURFACE LOCATION: NWSE SEC 27 - T35N - R7W 1485' FSL 1900' FEL
BOTTOM HOLE LOCATION: SAME AS SURFACE LOCATION
LATITUDE: 37.26928903 LONGITUDE: -107.6207015
NEAREST ADDRESS: 795 CR 505
CONTROL CENTER 24 HR. PHONE #: 970-247-6916
EMERGENCY CONTACT #: 911

Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: Streeter B 2
Location ID: 326590



8/23/24
+37.269243,-107.620365
129° SE

Inspection Photos
Location Name: Streeter B 2
Location ID: 326590



+37.269356,-107.621446
8/23/24
269° W

Photo 3. Reference area comprised of Squirreltail, Broom snakeweed and pine.