

Inspection Photos

August 23rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 325935

Inspection Document #: 714001147

La Plata County, CO

Township: NESW 27 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Streeter B1
Location ID: 325935



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: Streeter B1
Location ID: 325935



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Stormwater CA identified in the previous inspection doc #693904490 has been addressed/resolved.

API #: 067-07195

Inspection Photos
Location Name: Streeter B1
Location ID: 325935



Photo 3. View of the eastern interim reclamation area facing north.

Inspection Photos
Location Name: Streeter B1
Location ID: 325935



Photo 4. Reference area comprised of Smooth brome, Gambel oak and Pine.

