

Caerus Piceance LLC  
Figure Four Unit 8003D A16 498  
Location ID: 311849



When replaced additional information will be required



When replaced additional information will be required



Caerus Piceance LLC  
Figure Four Unit 8003D A16 498  
Location ID: 311849



Debris



Debris. Unused equipment.



Caerus Piceance LLC  
Figure Four Unit 8003D A16 498  
Location ID: 311849



Debris. Unused equipment.



Debris



Caerus Piceance LLC  
Figure Four Unit 8003D A16 498  
Location ID: 311849



Debris



Debris

Caerus Piceance LLC  
Figure Four Unit 8003D A16 498  
Location ID: 311849



Missing required information



Missing required information





**Caerus Piceance LLC  
Figure Four Unit 8003D A16 498  
Location ID: 311849**



**Unused equipment**



**Location from North entrance**



**Caerus Piceance LLC**  
**Figure Four Unit 8003D A16 498**  
**Location ID: 311849**



**Location from Southwest corner**



**Location from Southeast corner**