

Caerus Piceance LLC  
Figure Four Unit 8008D A16 498  
Location ID: 311850



When replaced additional information will be required



When replaced additional information will be required

Caerus Piceance LLC  
Figure Four Unit 8008D A16 498  
Location ID: 311850



Debris



Debris. Unused equipment.

Caerus Piceance LLC  
Figure Four Unit 8008D A16 498  
Location ID: 311850



Debris. Unused equipment.



Debris

Caerus Piceance LLC  
Figure Four Unit 8008D A16 498  
Location ID: 311850



Debris



Debris

Caerus Piceance LLC  
Figure Four Unit 8008D A16 498  
Location ID: 311850



Missing required information



Missing required information



**Caerus Piceance LLC  
Figure Four Unit 8008D A16 498  
Location ID: 311850**



**Unused equipment**



**Location from North entrance**

**Caerus Piceance LLC  
Figure Four Unit 8008D A16 498  
Location ID: 311850**



**Location from Southwest corner**



**Location from Southeast corner**