

Caerus Piceance LLC
Freedom Unit-297 17-A
Location ID: 335713



When replaced additional information is required.



Well signs missing required information

**Caerus Piceance LLC
Freedom Unit-297 17-A
Location ID: 335713**



Debris



Debris. Equipment not in use. Open to wildlife.

Caerus Piceance LLC
Freedom Unit-297 17-A
Location ID: 335713



Debris



Relief riser missing cap

Caerus Piceance LLC
Freedom Unit-297 17-A
Location ID: 335713



Well pad from Northeast corner



Well pad from Southwest corner

Caerus Piceance LLC
Freedom Unit-297 17-A
Location ID: 335713



Well pad from Northwest entrance



Production facility from Northwest entrance