

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 23-19 Pad

Location ID: 335433



Photo # 7720 From entrance to location




Photo # 7721 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 23-19 Pad

Location ID: 335433



Sep 3, 2024 at 12:13:58 PM
CO



Sep 3, 2024 at 12:12:10 PM
CO

Photo # 7722 Location

Photo # 7723 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 23-19 Pad

Location ID: 335433



Photo # 7724 Location



Photo # 7725 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 23-19 Pad

Location ID: 335433



Photo # 7726 Location



Photo # 7727 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 23-19 Pad

Location ID: 335433



Photo # 7728 Wellhead sign laying on ground/not conspicuously posted



Photo # 7729 Open ended load line