

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403908750

Date Received:
09/04/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Caerus

COGCC.inspections@caerusoilandgas.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708904464

Inspection Date: 08/29/2024

FIR Submit Date: 09/01/2024

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334069

Location Name: SHIDELER-68S93W Number: 1SWNE County: _____

Qtrqtr: SWNE Sec: 1 Twp: 8S Range: 93W Meridian: 6

Latitude: 39.398990 Longitude: -107.719270

FACILITY - API Number: 05-045- -00 Facility ID: 334069

Facility Name: SHIDELER-68S93W Number: 1SWNE

Qtrqtr: SWNE Sec: 1 Twp: 8S Range: 93W Meridian: 6

Latitude: 39.398990 Longitude: -107.719270

CORRECTIVE ACTIONS:

1 ☒ CA# 198243

Corrective Action: All load lines will be capped or plugged

Date: 09/08/2024

Response: CA COMPLETED

Date of Completion: 09/03/2024

Operator
Comment: Installed camlock fitting and plug. See Photos.

ECMC Decision: Approved pending re-inspection

Date: 09/08/2024

Date of Completion: 09/03/2024

Installed rain cap on vent. See photos.

Approved pending re-inspection

Signed:

Date: 9/4/2024 6:43:43 AM

<u>Document Number</u>	<u>Description</u>
403908750	FIR RESOLUTION SUBMITTED
403908751	Installed plug in load line.
403908752	Installed rain cap.

Page 2 of 2