

Inspection Photos

Location Name: KEHN USX AC-67N63W/35SWSW

Location ID: 310264



Photo #1

KEHN USX AC-67N63W/35SWSW pad

Battery site

Active

Entrance to Battery / Wellsite(s)



Photo #2

KEHN USX AC-67N63W/35SWSW pad

Battery site

Active



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: KEHN USX AC-67N63W/35SWSW

Location ID: 310264



Photo #3

KEHN USX AC-67N63W/35SWSW pad

Battery site

Active

Crude oil, Produced H2O tank(s): SE corner



Photo #4

KEHN USX AC-67N63W/35SWSW pad

Battery site

Active

ECD(s), Separator(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: KEHN USX AC-67N63W/35SWSW

Location ID: 310264



Photo #5

KEHN USX AC-67N63W/35SWSW pad

Battery site

Active

Facility / Battery sign




Photo #6

Kehn USX AC 35-13 (123-26152) Wellsite

Producing | PR



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: KEHN USX AC-67N63W/35SWSW

Location ID: 310264

Associated Well(s)	API	Status
1. Kehn USX AC 35-13	123-26152	PR

Photo #7

KEHN USX AC-67N63W/35SWSW Battery site

Active

Associated Well(s)

Producing | PR



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources