



**Note**—Report all defects in machinery, coring, slope tests and injuries under **Remarks**

DATE Aug 20-21-22-75 RIG NO. \_\_\_\_\_

WELL NO.  
26

Brick

RIG NO

RECEIVED

COUNTY STATE  
Rio Blanco Colo.

OCT 28 1975

TO		FROM	TO	FORMATION	EMPLOYEE	OCCUPATION	HOURS		RATE
TO	FROM	TO	FORMATION	REG			O.T.		
2	1964	2264	Shale	21	W.R. Burgett	DRLR	9		
					Ray Holman	DKM	9		
					Carl Akin	MM	9		
						HLP			
						HLP			
DEFINITION									
CORE NO.									
NET NO.									
CORE HEAD NO.									
CORE NO. & DESCRIPTION									

1. Air Service Rig  
7 hrs. Delg.  
1 hr. Blowing holes

Holoquit Disting. 2736

Received 300 Gal Propan 9360

TOLP	FROM	TO	FORMATION	EMPLOYEE	PATION	REG.	O.T.	RATE
3	2264	2319	Douglas Level Meele 70 ft. no Returns	W.R. Burgett Ray Holman Carl A. Kiss	DRLR	9		
					DKM	9		
					NM	9		
					HLP			
					HLP			
CONE NO.	SET NO.		CORE HEAD NO.	CORE NO. & DESCRIPTION				

2 hrs. Drdg. without Returns  
4 hrs. Working Pipe out of Hole  
3 hrs. Laying Down V.P.

APPROVED BY FIELD SUPERINTENDENT

file