

Inspection Photos

08/21/2024

Operator: SWN PRODUCTION COMPANY LLC

#10396

Location ID: 313326

Inspection Doc: 696206160

Moffat County, CO

Aaron Trujillo
Reclamation Work Lead
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313326



Photo 1: Photos taken from the southeast end of the Location, facing south and east. Photos show access road has not been reclaimed in accordance with 1004 Requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313326



Photo 2: Photos taken from the east end of the well site location, facing southwest and northwest. Location has been seeded with non-native species that are not reflective of the reference area.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313326



Photo 3: Photos taken from the well site Location. Photos examples showing Noxious weeds (Scotch thistle, Canada thistle) observed established throughout the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313326



Photo 4: Photos taken from the south end of the Location. Photos show utility equipment on and leading to location has not been removed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313326



Photo 5: Photos taken from the 2nd pad adjacent to the well site on the southeast end of the Location. Though vegetated, it is apparent that road base/gravel material removal and compaction alleviation had not been performed and area reclaimed pursuant to 1004 requirements



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313326



Photo 6: Photo taken from the southeast end of the Location, next to the 2nd graveled pad. Photos show utility equipment on and leading to location has not been removed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources