

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/1NWSE

Location ID: 335920

Date: 8/29/2024



Location Entrance – Photo #03213



Wellheads – Photo #03219

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/1NWSE

Location ID: 335920

Date: 8/29/2024



Separators – Photo #03217



Tank Battery – Photo #03215

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/1NWSE

Location ID: 335920

Date: 8/29/2024



**Damaged Fencing – Photo #03218**



**Open-Ended Line – Photo #03221**