

## Inspection Photos

Location: CAERUS PICEANCE LLC ROMAS-68S96W/1NESW

Location ID: 334104

Date: 8/29/2024



Entrance to location - Photo #05199



Location - Photo #05247



## Inspection Photos

Location: CAERUS PICEANCE LLC ROMAS-68S96W/1NESW

Location ID: 334104

Date: 8/29/2024



Wellheads - Photo #05200



Separators - Photo #05209

## Inspection Photos

Location: CAERUS PICEANCE LLC ROMAS-68S96W/1NESW

Location ID: 334104

Date: 8/29/2024



Tank battery - Photo #05221



NW corner of location - Photo #05235

## Inspection Photos

Location: CAERUS PICEANCE LLC ROMAS-68S96W/1NESW

Location ID: 334104

Date: 8/29/2024



NE corner of location - Photo #05236



SE corner of location - Photo #05241

## Inspection Photos

Location: CAERUS PICEANCE LLC ROMAS-68S96W/1NESW

Location ID: 334104

Date: 8/29/2024



Debris - Photo #05206



Debris - Photo #05208

## Inspection Photos

Location: CAERUS PICEANCE LLC ROMAS-68S96W/1NESW

Location ID: 334104

Date: 8/29/2024



Aug 29, 2024 at 11:09:50 AM  
+39.376738,-108.061735 ±4.72m  
Parachute



Aug 29, 2024 at 11:10:54 AM  
+39.376738,-108.061735 ±4.72m  
Parachute

Debris - Photo #05216

Debris - Photo #05218

## Inspection Photos


Location: CAERUS PICEANCE LLC ROMAS-68S96W/1NESW

Location ID: 334104

Date: 8/29/2024



Debris - Photo #05219



Debris - Photo #05227

## Inspection Photos

Location: CAERUS PICEANCE LLC ROMAS-68S96W/1NESW

Location ID: 334104

Date: 8/29/2024



Debris - Photo #05228



Debris - Photo #05230

## Inspection Photos

Location: CAERUS PICEANCE LLC ROMAS-68S96W/1NESW

Location ID: 334104

Date: 8/29/2024



Debris - Photo #05234



Debris - Photo #05239

## Inspection Photos

Location: CAERUS PICEANCE LLC ROMAS-68S96W/1NESW

Location ID: 334104

Date: 8/29/2024



Debris - Photo #05240



Debris - Photo #05244

## Inspection Photos

Location: CAERUS PICEANCE LLC ROMAS-68S96W/1NESW

Location ID: 334104

Date: 8/29/2024



Open ended load line - Photo #05225



Stored supplies - Photo #05229



## Inspection Photos

Location: CAERUS PICEANCE LLC ROMAS-68S96W/1NESW

Location ID: 334104

Date: 8/29/2024



Wildlife hazard - Photo #05231

