

# Inspection Photos

August 21st, 2024

Operator: Kinder Morgan - 46685

Location ID: 313524

Inspection Document #: 714001159

Montezuma County, CO

Township: SESW 7 38N 18W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: McElmo Dome Unit 7-38-18 CC 1

Location ID: 313524



8/21/24  
+37.587718,-108.855926  
225° SW

**Photo 1.** View of project area taken from the access point facing center. Note: flat part of project area has been disturbed and gravelled and is no longer vegetated.

Inspection Photos

Location Name: McElmo Dome Unit 7-38-18 CC 1

Location ID: 313524



**Photo 2.** View of cut and fill slopes on location that are vegetated to ECMC's 80% of reference area standard.

Inspection Photos

Location Name: McElmo Dome Unit 7-38-18 CC 1

Location ID: 313524



8/21/24

+37.587718,-108.855926

355° N



**Photo 3.** Additional view of flat portion of project area taken from the southern edge facing center.