

Inspection Photos

08/21/2024

Operator: SWN PRODUCTION COMPANY LLC
#10396

Location ID: 313148

Inspection Doc: 696206167

Moffat County, CO

Aaron Trujillo
Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313148



August 21, 2024



August 21, 2024

Photo 1: Photos from the Location entrance on the south end of hte Location; photo left facing south, photo right facing north. Photos show access road has not been reclaimed. Photos also show areas of the access road where work is evident, and where Operator appears to have only pushed/dumped/placed soil on top of of the road prior to performing seeding activities; gravel/compaction evident beneath placed soils.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313148



Photo 2: Continued from photo 1. Photos show areas of the access road where work is evident, and where Operator appears to have only pushed/dumped/placed soil on top of of the road prior to performing seeding activities; gravel/compaction evident beneath placed soils.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313148



August 21, 2024

Photo 3: Photos show access road has not been reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313148



Photo 4: Photos show Utility equipment on, and leading to, the Location has not been removed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313148



Photo 5: Photo taken from the south end of the Location, adjacent to the access road. Photo shows riser equipment remaining.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313148



Photo 6: Photos taken from the Location. Photos examples showing Noxious weeds (Scotch thistle) observed established throughout the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources