

Inspection Photos

08/21/2024

Operator: SWN PRODUCTION COMPANY LLC
#10396

Location ID: 313338

Inspection Doc: 696206169

Moffat County, CO

Aaron Trujillo
Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313338



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location from south, southwest, northwest to north.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313338



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313338



Photo 3: Photos show Utility equipment on, and leading to, the Location has not been removed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313338



Photo 4: Photo left taken from the Location entrance, facing east; photo right taken from the access road turn-off, facing west. Photos show access road leading to the Location has not been reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313338



August 21, 2024

Photo 5: Photo taken from the Location entrance. Photo shows signage with incorrect Operator information. Signage requires updating/maintaining, or removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313338



August 21, 2024



August 21, 2024

Photo 6: Photos taken from the Location. Photos examples showing Noxious weeds (Scotch thistle) observed established throughout the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC #10396

Location ID: 313338



Photo 7: Photos taken from the Location. Photos examples showing Noxious weeds (Scotch thistle) observed established throughout the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources