

Inspection Photos

08/21/2024

Operator: QUICKSILVER RESOURCES INC -
10255

Location ID: 313334

Inspection Doc: 696206176

Moffat County, CO

Aaron Trujillo
Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QUICKSILVER RESOURCES INC - 10255

Location ID: 313334



Photo 1: Photos 1-2 taken from the northeast end of the Location. Photos provide an overview of the Location from southeast, south, southwest to west. Photos also examples showing noxious weed (scotch thistle) establishment observed throughout the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QUICKSILVER RESOURCES INC - 10255

Location ID: 313334



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QUICKSILVER RESOURCES INC - 10255

Location ID: 313334



Photo 3: Photos taken from the Location, next to the well marker. Photo shows riser and pipe equipment remaining on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QUICKSILVER RESOURCES INC - 10255

Location ID: 313334



Photo 4: Photos 4-5 taken from the eastern areas of the Location. Photos examples showing areas that remain predominantly bare, or vegetated by undesirable plant species. Areas are not progressing towards 1004 revegetation standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QUICKSILVER RESOURCES INC - 10255

Location ID: 313334



August 21, 2024

Photo 5: See comments under photo 4.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources