

# Inspection Photos

08/21/2024

**Operator:** SWN PRODUCTION COMPANY LLC -  
10396

**Location ID:** 313347

**Inspection Doc:** 696206178

Moffat County, CO

Aaron Trujillo  
Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313347



**Photo 1:** Photos taken from the southwest end of the Location, facing north and east. Vegetation on Location is predominantly undesirable and noxious plant species such as Cheatgrass, Kochia, Russian thistle and Scotch thistle.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources



## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313347



August 21, 2024

**Photo 2:** Photos taken from the southwest end of the Location, facing east. Photo shows access road has not been reclaimed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313347



**Photo 3:** Vegetation on Location is predominantly undesirable and noxious plant species such as Cheatgrass, Kochia, Russian thistle and Scotch thistle.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313347



**Photo 4:** Vegetation on Location is predominantly undesirable and noxious plant species such as Cheatgrass, Kochia, Russian thistle and Scotch thistle.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources