

Inspection Photos

08/21/2024

Operator: SWN PRODUCTION COMPANY LLC -
10396

Location ID: 313329

Inspection Doc: 696206180

Moffat County, CO

Aaron Trujillo
Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313329



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview from south, southwest, northwest to north.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources


Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313329



August 21, 2024



August 21, 2024

Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313329



August 21, 2024

Photo 3: Photos shows bare areas of the Location that did not get seeded.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313329



Photo 4: Reclamation work at the access road/location entrance on the east end of the Location inadequate; Operator appears to have seeded directly into the road; compaction issues and gravel remain evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313329




Photo 5: Photo shows utility equipment on, and leading to, the Location has not been removed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources