

# Inspection Photos

08/21/2024

**Operator:** SWN PRODUCTION COMPANY LLC -  
10396

**Location ID:** 313350

**Inspection Doc:** 696206182

Moffat County, CO

Aaron Trujillo  
Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313350



**Photo 1:** Photos 1-2 taken from the Location entrance on the northeast end of the Location. Photos provide an overview from southeast, south, west to northwest. Photos also show Location has not been recontoured/regraded pursuant to 1004 requirements; cut/fill slopes remain.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313350



August 21, 2024



August 21, 2024

**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313350



**Photo 3:** Photo example showing fill slopes remaining. Location has not been recontoured/regraded and reclaimed in accordance with 1004 Rules.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313350



**Photo 4:** Photo taken from the Location. Photo example showing gravel/road base material remaining on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313350



August 21, 2024

**Photo 5:** Signage on Location posted with incorrect Operator information.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313350



August 21, 2024

**Photo 6:** Photo taken from the northeast end of the Location, facing southeast. Photo shows access road leading to the Location has not been reclaimed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313350



**Photo 7:** 2023 Google Earth aerial imagery. Location and access road (red line) has not been decompacted, recontoured/regraded and reclaimed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources