

**Operator:** 8 North

**Location Name:** DF Ranch PC GK 17-99HZ

**Loc ID:** 418692

**Inspection:** 691400016




































**CA:** Produced water tank does not list capacity. Install sign to comply with Rule 210.d.

**CA Resolution:** Operator has appropriately installed signage on the produced water tank to display the capacity.

**CA:** Trash in treater house. Comply with Rule 603.f .

**CA Resolution:** Operator has appropriately cleared debris/trash from the location to comply with the 600 series.

**CA:** Stained soil at wellhead, south of wellhead, at base of pumpjack, under pumpjack weights, in motor room, at load out & multiple in treater house. Comply with Rule 603.f.

**CA Resolution:** Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed.