



Where Technical Expertise Meets Environmental Solutions

Fundare

Horsetail 30H Vegetation Assessment Photo Doc

Drafted By: Levi Kirk



Sep 4, 2024 1:46:19 PM
40.81138287N 103.80144245W

Photo Date 9/4/2024- Drill Pad post reclamation



Photo Date 9/4/2024- Reference Area