

Inspection Photos
Location: Deer Foot 13-18
Location ID: 309161
API # 05-071-09184




Photo 1 – Well placard on meter house

Photo 2 – Wellhead and equipment

Inspection Photos
Location: Deer Foot 13-18
Location ID: 309161
API # 05-071-09184



Photo 3 – Stained soils at wellhead



Photo 4 – At the time of inspection Noxious weeds were observed @ 37.25666, -104.93503

Inspection Photos
Location: Deer Foot 13-18
Location ID: 309161
API # 05-071-09184



Photo 5 – Location and meter house