

Inspection Photos

08/21/2024

Operator: SWN PRODUCTION COMPANY LLC -
10396

Location ID: 313155

Inspection Doc: 696206192

Moffat County, CO

Aaron Trujillo
Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313155



Photo 1: Photos taken from the south end of the Location, facing northwest and northeast. Location has not met 1004 revegetation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313155



Photo 2: Photos examples showing vegetation on the Location has not achieved uniform establishment. Erosion degradation due to runoff evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313155



Photo 3: Photos examples of Noxious weeds (Scotch thistle) observed on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources




Photo 8: Google earth aerial imagery. Top photo dated 2023; bottom 1994. Yellow lines represent access roads that existed prior to Oil and Gas disturbances. Red lines represent access roads constructed to Oil and Gas Locations subject to 1004 final reclamation requirements. Access road to the Walker 3-4 did not pre-exist the Location.