

**Operator: 8 North**

**Location Name: BASHOR PC GQ 15-13**

**Loc ID: 417826**

**Inspection: 684904669**




Exhibit A





Exhibit B





**Exhibit C**

**CA:** Stained soil at wellhead Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

**CA Resolution:** Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed.






Exhibit A

**CA:** Stained soil in treater house Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

**CA Resolution:** Operator has provided photo evidence to show that the stained soil in treater house has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed.