

Operator: 8 North

Location Name: DF Ranch PC GK 17-99HZ


Loc ID: 418692

Inspection: 696301041





















CA: Stained Soil at gas engine. Properly dispose of oily waste in accordance with 907.e

CA Resolution: Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed.