

## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 6-11 (J6SE) Pad

Location #: 324343



Photo # 8599 From Entrance to location



Photo # 8600 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 6-11 (J6SE) Pad

Location #: 324343



**Photo # 8601 Location**



**Photo # 8602 Wellhead lacks required signage/does not comply with CECMC rules**