

Inspection Photos


Location: CAERUS PICEANCE LLC NPM/M33-496 PAD

Location ID: 335937

Date: 9/4/2024



Entrance to location - Photo #05373



Plugging Operations - Photo #05374

Inspection Photos

Location: CAERUS PICEANCE LLC NPM/M33-496 PAD

Location ID: 335937

Date: 9/4/2024



P&A well - Photo #05375



Plugging Operations - Photo #05376

Inspection Photos

Location: CAERUS PICEANCE LLC NPM/M33-496 PAD

Location ID: 335937

Date: 9/4/2024



Plugging Operations/No wellhead signage - Photo #05387



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources