

Operator: *Highpoint Operating Corp LLC*

Location Name: Anschutz Equus Farms 4-62-33 NWNW

Loc ID: 437854

Inspection: 717700360



Exhibit A




Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F



Exhibit G



Exhibit H



Exhibit I



Exhibit J




Exhibit K



Exhibit L



Exhibit M



Exhibit N




Exhibit O



Exhibit P



Exhibit Q



Exhibit R



Exhibit S

CA: Pits around the location need to have capacity labels. Install sign to comply with Rule 605.h.

CA Resolution: Operator has addressed the issue and capacity labels on all pits have been replaced in order to comply with Rule 605.h.

CA: Stained soil next to the compressor needs to be removed. Properly dispose of oily waste in accordance with 905.e

CA Resolution: Operator has addressed the issue and the soil next to the compressor has been cleaned up in order to comply with Rule 905.e.

CA: Unmarked risers in multiple spots need to be marked. Comply with the 1100 Rules.

CA Resolution: Operator has addressed the issue and future use tags have been installed on all unused risers in order to comply with the 1100 series.