

Final Reclamation and Stormwater Inspection

Date: 08/27/2024

Operator: PDC ENERGY INC - 69175

Location ID: 319160

Inspection Document #: 708201565

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Weber 1-26
Location ID: 319160



Photo 1. Facing northwest from the start of the access road. The access road does not appear to have been reclaimed with evidence of road base material observed.

Inspection Photos
Location Name: Weber 1-26
Location ID: 319160



Photo 2. Facing south from the northeastern portion of the former location. The location consists mainly of bare/exposed soils. Additional reclamation activities are required.

Inspection Photos
Location Name: Weber 1-26
Location ID: 319160



Photo 3. Facing southeast from the northwestern portion of the location; see comments in Photo 2.

Inspection Photos
Location Name: Weber 1-26
Location ID: 319160



Photo 4. Facing northeast from the southwestern portion of the location; see comments in Photo 2.

Inspection Photos
Location Name: Weber 1-26
Location ID: 319160



Photo 5. Facing east from the access road; see comments in Photo 1.