

State of Colorado
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

ECMC RECEPTION

Receive Date:

06/20/2024

Document Number:

403649733

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 47120 Contact Person: Erik Mickelson
Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (970) 929-4306
Address: P O BOX 173779 Fax: ()
City: DENVER State: CO Zip: 80217-3779 Email: Erik_Mickelson@oxy.com

Identification Information

API Number: 05 - - ECMC Facility ID: 485209 Initial Form 19 or 27 Document number:
Facility Name: LIZZY Facility Number: 8-36HZ Facility Type: LOCATION
Location QtrQtr: SENE Section: 36 Township: 1N Range: 68W Meridian: 6
County: WELD Field Name:
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: Absaroka Solutions Agent Name: Jordan Fleming Title: Environmental Professional
Phone Number: 7202448469 Email: jordan.fleming@absarokasolutions.com

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 772184 Facility Name: Xiong 94044 Facility Type: Domestic Well
Location: QtrQtr: SWNW Sec: 1 Twp: 1S Range: 68W Meridian: 6
County Name: ADAMS Latitude: 39.995735 Longitude: -104.956783

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 115928 Document Name: Size of file in bytes: 31232 File Name: 2023_10_25_Xiong 94044 Trip Blank SGS ECMC.xls
SampleType: Matrix:
Facility ID: 772184 Sample ID: 655181 Sample Name: Xiong 94044 Sample Date: 10/25/2023
Collection Point: TB Matrix: WATER Pre Post: Voluntary baseline sample
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: Accutest Lab Sample ID: DA59633-1

Batch ID: 115929		Document Name: Size of file in bytes: 35840		File Name: 2023_10_25_Xiong 94044 Isotech NG4 ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 772184	Sample ID: 655183	Sample Name: Xiong 94044		Sample Date: 10/25/2023	
Collection Point: Dom		Matrix: WATER	Pre Post: Voluntary baseline sample		
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 896734		

Batch ID: 119906		Document Name: Size of file in bytes: 25600		File Name: 2023_10_25_Xiong 94044 SGS DRO ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 772184	Sample ID: 659467	Sample Name: XIONG 94044		Sample Date: 10/25/2023	
Collection Point: Dom		Matrix: WATER	Pre Post: Voluntary baseline sample		
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA59619-1		

Batch ID: 115926		Document Name: Size of file in bytes: 79872		File Name: 2023_10_25_Xiong 94044 SGS ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 772184	Sample ID: 655179	Sample Name: Xiong 94044		Sample Date: 10/25/2023	
Collection Point: Dom		Matrix: WATER	Pre Post: Voluntary baseline sample		
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA59619-1		

Batch ID: 115929		Document Name: Size of file in bytes: 35840		File Name: 2023_10_25_Xiong 94044 Isotech NG4 ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 772184	Sample ID: 655182	Sample Name: Xiong 94044		Sample Date: 10/25/2023	
Collection Point: Dom		Matrix: GAS	Pre Post: Voluntary baseline sample		
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 896734		

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
772184	403649738	2023_10_25_Xiong 94044 Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
772184	403649749	2023_10_25_Xiong_94044_Pre Post Purge.jpg	Photographs	JPG
772184	403649750	2023_10_25_Xiong_94044_Spigot.jpg	Photographs	JPG
772184	403649747	2023_10_25_Xiong_94044_FS_ECMC.pdf	Field Data Report	PDF
772184	403649740	2023_10_25_Xiong 94044 SGS.pdf	Analytical Laboratory Report	PDF
772184	403649751	2023_10_25_Xiong_94044_Wellhead Spigot Location.jpg	Photographs	JPG
772184	403649737	2023_10_25_Xiong 94044 Isotech NG4.pdf	Analytical Laboratory Report	PDF
772184	403649752	2023_10_25_Xiong_94044_Wellhead.jpg	Photographs	JPG

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	09/09/2024
Total: 1 comment(s)		