

## Inspection Photos

Location: CAERUS PICEANCE LLC N. PARACHUTE-65S96W/5NENE

Location ID: 335909

Date: 9/5/2024



Entrance to location - Photo #05393




Wellheads - Photo #05394

## Inspection Photos

Location: CAERUS PICEANCE LLC N. PARACHUTE-65S96W/5NENE

Location ID: 335909

Date: 9/5/2024



Wellhead missing signage - Photo #05395



Gas lift/Sales - Photo #05405

## Inspection Photos

Location: CAERUS PICEANCE LLC N. PARACHUTE-65S96W/5NENE

Location ID: 335909

Date: 9/5/2024



Tank battery/No signage - Photo #05408



NE corner of location - Photo #05418

## Inspection Photos

Location: CAERUS PICEANCE LLC N. PARACHUTE-65S96W/5NENE

Location ID: 335909

Date: 9/5/2024



SE corner of location - Photo #05419



Debris - Photo #05420

## Inspection Photos

Location: CAERUS PICEANCE LLC N. PARACHUTE-65S96W/5NENE

Location ID: 335909

Date: 9/5/2024



Debris - Photo #05421



Debris - Photo #05423

## Inspection Photos

Location: CAERUS PICEANCE LLC N. PARACHUTE-65S96W/5NENE

Location ID: 335909

Date: 9/5/2024



Debris - Photo #05424



Debris - Photo #05425

## Inspection Photos

Location: CAERUS PICEANCE LLC N. PARACHUTE-65S96W/5NENE

Location ID: 335909

Date: 9/5/2024



Debris - Photo #05426



Debris - Photo #05430